

| New Logic | | | | |
|----------------|-------------|----------|----------|----------|
| Lattice | ispLSI2032A | LC5512MB | LC5512MC | LC5512MV |
| Xilinx | XC2C32 | | | |

| New Memory | | | | |
|------------------------|---------------|------------------|-------------|--------------|
| AMD | Am29BDD160GB | Am29F016 F | Am29F032B F | Am29LV017B F |
| | Am29LV116BT F | Am29LV116DB F | | |
| Atmel | AT25F2048 | AT49BV802A | AT49BV802AT | |
| Catalyst | CSI25040 | | | |
| Fairchild | NM93C86A | | | |
| Fujitsu | MBM29PL12LM | MBM29PL32BM-PFTN | | |
| Macronix | MX26L6420 | | | |
| Micron | MT28F128J3 | | | |
| NexFlash | NX25P10 | NX25P20 | NX25P40 | |
| Ramtron | FM1608 | | | |
| Renesas | R5F61527FP | R5F61657FT | | |
| Rohm | BR93L56 | | | |
| Spansion | S25FL002D | | | |
| SST | 25VF020 | 49LF004B | | |
| STMicroeleconic | M24C02W-DW | M29F800DB N | M29W800DT N | M50FW016 N |
| | M58LV064B | | | |
| Toshiba | TC58FVM7B2ATG | TMP93PW32F | | |

| New Microcontroller | | | | |
|------------------------|---------------|----------------|---------------|----------------|
| Analog | ADM 1062 | ADM 1066 | | |
| Atmel | AT89C51ED2RD | AT89C51ED2SM | AT89S51 | ATmega162 |
| | ATmega169 | ATmega8535 | | |
| Microchip | PIC16C620SS | PIC16F627A | PIC16F684 | PIC16F688 |
| | PIC16LF76 | PIC16LF872 | PIC16LF876A | PIC16LF88 |
| | PIC18F1320 | | | |
| Motorola | MC68HRC705J1A | MC9S08Gx32FB | MC9S08Gx32FU | MC9S08Gx60FB |
| | MC9S08Gx60FU | MC9S12Dx512 PV | | |
| National | COP8CCE9IMT | COP8CCR9IMT | | |
| NEC | D78F0034AGB | D78F0134AGB | D78F0134GB | D78F0138AGB |
| | D78F0703 | D78F9456GB | | |
| Philips | 87LPC778 N | 87LPC778DH | OM836xH/Nx/3 | OM836xH/Nx/4 |
| | OM836xH/Nx/5 | OM837x/Nx/1 | OM837x/Nx/2 | OM837x/Nx/A |
| | PCF7921ATS | TDA9340/Nx/1 | TDA9340/Nx/2 | TDA9345/Nx/1 |
| | TDA9345/Nx/2 | TDA9347/Nx/1 | TDA9347/Nx/2 | TDA937x/Nx/2 |
| | TDA954xH/Nx/1 | TDA954xH/Nx/2 | TDA955x/Nx/1 | TDA955x/Nx/2 |
| | TDA955x/Nx/3 | TDA956x/Nx/3 | TDA956x/Nx/4 | TDA956x/Nx/5 |
| | TDA958x/Nx/3 | TDA959x/Nx/3 | TDA959x/Nx/4 | TDA959x/Nx/5 |
| Renesas | HD64F2138FA | HD64F2148ATE | HD64F2339F | HD64F2378VFQ |
| | HD64F2552F | HD64F3694FX | HD64F7058F | M30201F6TFP |
| | M30620FCP FP | M30624FGN FP | M3062GF8N FP | M306N4FCT FP |
| | M37733EHB FP | | | |
| STMicroeleconic | ST72F521M9T | ZPSD302-B | | |
| Texas Inst | MSP430F449 | TMS320F2810 | TMS470R1VF67A | TMS470R1VF336A |
| Zilog | Z8F6421AN | Z8F6421PM | Z8F6421VN | Z8F6422VS |
| | Z8F6422AR | Z8F6423FT | | |